


Reconstruction of the side



Legend

- Recovered timbers of the port side
- Recovered timbers of the starboard side
- Grooves with nails for the clinker fastenings
- Sintel-clamped parts of the clinker seams on the outside

Reconstruction drawing

Global, provisional reconstruction of the side of the Doel-1 cog, combining the recovered parts of the shell strokes on the starboard and port sides. The clinker fastenings are nailed at regular intervals, though occasionally nails occur in pairs. The cracks in the planks closed with clamped moss caulking were not recorded during salvage and hence are not drawn.

